

Assembly Instructions

1. Place worksurface on a soft surface to protect from damage.
Fig.1
2. Align leg mounting plate with pre-drilled holes on curved side on the back of the worksurface and attach using (12) Phillips screws with long side of caster assembly facing front of desk.
Fig.1
3. Align modesty panel with pre-drilled holes along back of desk and mount with (6) Phillips screws. Fig.1
4. Insert threaded studs into worksurface and thread tubes onto studs. Fig.1
5. Place lectern on top of tube assemblies and mount with (4) 5/16" Phillips screws with lock washers. Fig.2
6. Carefully flip desk assembly upright.

Fig. 1





Fig. 2



Note: Hinges should always align with the outside of the desk.



Tools Needed



power drill



#2 Phillips
driver



(18) 1" Phillips
wood screws



(4) 5/16" Phillips
screws



(4) internal tooth
locking washers



(4) threaded studs